## Poole Harbour Habitat Creation Scheme – The Moors at Arne

Ridge - Drainage and groundwater - Interim Evaluation




#### Introduction and objectives

- This presentation is intended to set out our current understanding of drainage and groundwater beneath Ridge and the relationship these may have with our proposed scheme
- We have adapted and developed our investigations according to concerns raised by the community
- This presentation offers a review of the work carried out and represents an insight into our studies and site investigations to date
- We are continuing to gather data and our interpretation may be expected to evolve further

#### Surface Drainage


- Hydrological catchment
- Natural "off slope" drainage
- Surface
   water
   drainage
   impacts/
   intercepts
   natural
   overland
   flow



# Surface water drainage catchments


- Road and roof drainage
- Soakaways to western part at top end of SW catchment
- Soakaways capture surface water runoff and recharge underlying shallow aquifer

 Boundaries of rainfall runoff catchments, indicating break of slope
Area of made ground acting as a barrier
Area connected to systems which drain to the North
Area connected to systems which drain to the East
Soakaways capture surface runoff from roofs and paved areas feeding water into the ground




## Hydrogeology -Regional perspective

- Poole Formation minor aquifer
- Succession of interbedded sands and clays, variable thickness and depth
- Recharge across outcrop to south and within the upper catchment of the Furzebrook
- Discharge northward toward Poole Harbour
- Clay layers "confine" lower parts of the sand aquifer such that water in the lower parts is under pressure
- When clays are "punctured" by boreholes, water under pressure rises to surface




#### Groundwater - initial conceptual understanding (schematic section)




Ground
Investigation Monitoring well
locations

BH18 (WS) Ridge Wharf Yachting Sentre Moors BH16 BH04 BH13-Caravan and Camping Site The Moors WS18 WS19 Site 1 Caravan and Camping Site WS01 WS20 Ridge Faitii ARNE HOAD WS16 Sunnyside Farm


**Installed water level loggers** 






#### Well Hydrograph Ridge vs Rainfall (mm)


- Smaller rainfall events (< c.5mm) little impact
- Larger or cumulative events.
   Rapid response in groundwater levels



#### Ground Investigation - well hydrographs- detail (one week of data)


- Is there a diurnal influence at Ridge?
- Wareham tidal range typically 1- 1.2m
- No evident tidal effect at Ridge WS17








#### Ground Investigation - well hydrographs- detail (one week)

- Is there a tidal effect further on to Arne Moor?
- Possible minor tidal effect (1- 2 cm?) at BH16
- Relationship appears to be inverse (i.e. a tidal low results in an increase in water level)
- This is suggestive of a pressure response not direct connectivity
- BH16 close to tidal channel/ harbour
- Response zone at 2-4m depth in "upper aquifer"









#### Thank You

Mike Barker

Principal Hydrogeologist



# JACOBS Ch2m: